

Fig.2




Fig.3




Fig.4




Fig.5




Fig.6




Fig.7(a)

$$\begin{pmatrix}
Rs \\
Gs \\
Bs
\end{pmatrix}
\longrightarrow
\begin{pmatrix}
Rw \\
Gw \\
Bw
\end{pmatrix}$$

Fig.7(b)

$$\begin{pmatrix} Rs \\ Gs \\ Bs \end{pmatrix} \longrightarrow A = \begin{pmatrix} 0.436 & 0.385 & 0.143 \\ 0.222 & 0.717 & 0.061 \\ 0.014 & 0.097 & 0.714 \end{pmatrix} \longrightarrow \begin{pmatrix} X \\ Y \\ Z \end{pmatrix}$$

Fig.7(c)

$$\begin{pmatrix}
RW \\
GW \\
BW
\end{pmatrix}
= 
\begin{pmatrix}
0.717 & 0.101 & 0.147 \\
0.259 & 0.725 & 0.017 \\
0 & 0.051 & 0.774
\end{pmatrix}
= 
\begin{pmatrix}
X \\
Y \\
Z
\end{pmatrix}$$

Fig.8




Fig.9




Fig.10




Fig.11




Fig.12




Fig. 13




Fig.14




Fig. 15

ENHANCEMENT LEVEL COEFFICIENT KL	SETTING
KL0	0
KL1	1
KL2	1. 5

Fig. 16

